

Sarsal San Marcos School Project

The Sarsal school is located in a remote village in the southern town of San Marcos de Colon, Honduras. This school is the most difficult school to travel to in San Marcos de Colon; in turn it has the most needs. The following are the necessities identified at the Sarsal School:

- A white board for the classroom
- There is a building next to the school that could be used as the cafeteria but needs to be repaired completely.
- Desks and furniture for the building that is not being used due to its bad condition
- The water source needs to be fixed
- Paint on the exterior to keep the moisture out when it rains.
- A fence to go around the school.
- The roof of cafeteria needs to be fixed/patched
- Cabinet doors for the shelves on the inside of the classroom



Potential Cafeteria



shelves need cabinet doors



outside of potential cafeteria

